



**BUREAU  
VERITAS**

**Certificate of Product Conformity**  
BVI.DOA.20.IND.343.49.CPC01

Job Description : **Conformity assessment of a product**  
Product Name : **Polyester Resin Concrete Manholes and Inspection Chambers**  
Product Range : **As per table below**  
Manufacturer : **Qatar German Pipes Company W.L.L.**  
Date of Inspection : **December 1-2, 2020**

S/N	Diameter of Manhole	Height Limit in Each Type in mm			
		Type 1	Type 2	Type 3	Type 4
As per Annexure # 1					

Scope of work:

1. Review of FPC (Factory Production Control) system and documentations (Section 8.3)
2. Inspections at Factory
3. Inspection on production process
4. Review of initial type testing results performed by other third party

Documents Referenced:

**BS EN 14636-2:2009** – Plastic piping systems for non-pressure drainage and sewerage – Polyester resin concrete (PRC)

Result of Inspection:

The product of PRC Inspection Chambers and Manholes manufactured and tested by Qatar German Pipes Company W.L.L. have been evaluated and found in conformity against the requirements of BS EN 14636-2:2009.

**This Certificate is issued under below condition:**

- This Certificate does not cover Design or Design Review
- It applies only to the quality system maintained in the manufacture of above referenced models.

**Note:** This certificate is based on the evaluation of PRC manholes DN 1200mm and DN 1500mm.

*This note is issued further to an inspection whose duration and scope were limited by the terms and conditions of the contract with BV principal. This note is NOT an indication that the item(s) is (are) fit for any specific purpose and does not release the manufacturer, supplier and any party from their respective duty, guarantee, obligation and/or indemnity relating to, without limitation, patents, workmanship, materials, safety, performance in operation and /or reliability.*

**This certificate is valid for 1 Year from the date of issue.**

Survey Carried out by : **Ayman Shaaban**  
Date of issue : **04/01/2021**  
Certificate Number : **01/2021**  
Inspection Center : **Doha, Qatar**

